Level-13, AJ Heights, Cha-72/1/d North Badda, Pragati Sarani Dhaka-1212, Bangladesh PABX: +880 2 41081863-6

uwww.rsc-bd.org⊢

Date: 15/03/2022

Subject: RMG Sustainability Council (RSC) Structural Safety Assessment Comfit

Composite Knit Ltd.(Unit-3) (10101)

For the attention of Factory Owner/Manager, Lead Brand, Responsible Participating Companies &

Union Colleagues

We are writing to inform you of the RMG Sustainability Council (RSC) Structural Safety Assessment

for the below factory.

Factory Name: Comfit Composite Knit Ltd. (Unit-3) (Account ID: 10101)

Address: Vannara Road, Po-Purbo Mouchak, Ps- Kaliakoir, Dist- Gazipur.

The Accord conducted an initial structural assessment at this facility on 07/05/2014. The RSC

conducted follow-up structural inspections last on 28/02/2022.

The factory has completed remediation on all structural issues identified in the Accord initial and

RSC follow-up structural inspection reports for this factory. Any color category associated with this

factory is no longer valid, and the RSC is satisfied that general compliance with our structural safety

standard is achieved.

Please note that this clearance is given based on the inspections conducted by the RSC and does not

cover any modifications, extensions etc. which have taken place after the initial inspection unless

specifically verified by the RSC. The factory must ensure the ongoing compliance with loading plans

and maintenance to ensure the integrity of the building. The RSC reserves the right to add further

structural findings in the future.

This letter is a reference to structural findings only. It does not reference fire and electrical findings.

Sincerely,

Iqbal M Hussain

Managing Director & Acting Chief Safety Officer

RMG Sustainability Council (RSC)